



BERGEON

Depuis 1791

Pièces de rechange

Ersatzteile

Spare-parts

Piezas de recambio

Poussoirs à déchasser

Ø 0.75 mm couleur jaune
Ø 0.85 mm couleur acier

En commandant: préciser le Ø.

Stößel zum Ausstossen

Ø 0.75 mm Gelbfarben
Ø 0.85 mm Stahlfarben

Bei Bestellung: Ø angeben.

Plunger


Ø 0.75 mm yellow colour
Ø 0.85 mm steel colour

When ordering: indicate the Ø.

Pulsadores para extraer

Ø 0.75 mm color amarillo
Ø 0.85 mm color acero

En el pedido: indicar el Ø.



| No | gr. | Pce Fr. / 100 | Pce Fr. / 10 | Pce Fr. |
|--------|-----|---------------|--------------|---------|
| 6819-1 | 15 | | | |

Goupilles de rechange

Ø 0.75 mm couleur jaune
Ø 0.85 mm couleur acier

En commandant: préciser le Ø.

Ersatzstifte

Ø 0.75 mm Gelbfarben
Ø 0.85 mm Stahlfarben

Bei Bestellung: Ø angeben.

Pins of replacement

Ø 0.75 mm yellow colour
Ø 0.85 mm steel colour

When ordering: indicate the Ø.

Clavijas de recambio

Ø 0.75 mm color amarillo
Ø 0.85 mm color acero

En el pedido: indicar el Ø.



| No | gr. | Pce Fr. / 100 | Pce Fr. / 10 | Pce Fr. |
|----------|-----|---------------|--------------|---------|
| 6819-1-G | 5 | | | |

Poussoir à chasser

Einsetzstößel

Insertion plunger

Pulsador para embutir



| No | gr. | Pce Fr. / 100 | Pce Fr. / 10 | Pce Fr. |
|--------|-----|---------------|--------------|---------|
| 6819-2 | 22 | | | |

Cales

No 1 (11mm), No 2 (8mm),
No 3 (5 mm), No 4 (5 - 4 mm),
En commandant: préciser le No.

Keil


Nr. 1 (11mm), Nr. 2 (8mm),
Nr. 3 (5 mm), Nr. 4 (5 - 4 mm),
Bei Bestellung: Nr. angeben.

Block

No 1 (11mm), No 2 (8mm),
No 3 (5 mm), No 4 (5 - 4 mm),
When ordering: indicate the No.

Calzas

No 1 (11mm), No 2 (8mm),
No 3 (5 mm), No 4 (5 - 4 mm),
En el pedido: indicar el No.



| No | gr. | Pce Fr. / 100 | Pce Fr. / 10 | Pce Fr. |
|--------|-----|---------------|--------------|---------|
| 6819-3 | 1 | | | |